

MATERIAL SAFETY DATA SHEET

For Welding Consumables and Related Products. Conforms to OSHA Hazard Communication Standard 29CFR 1910.1200

Date: 01/01/2012 MSDS No. 722

SECTION 1: IDENTIFICATION

Manufacturer/Supplier	Welding Material Sales, Inc. 1340 Reed Road Geneva, IL 60134 USA
Telephone Number	630-232-6421
Emergency Number	800-424-9300
Product Type	Gouging Carbons
Classification	Air Carbon Gouging Electrodes

SECTION 2: HAZARDOUS MATERIALS*

Important: This section covers the materials of which the products are manufactured. The fumes and gases produced during normal use of this product are covering in Section 5.

* The term "Hazardous Materials" should be interpreted as a term required and defined in OSHA Hazard Communication Standard 29CFR 1910-1200; however the use of this term does not necessarily imply the existence of any hazard.

INGREDIENTS	CAS #	Exposure Limit (mg/m ³) OSHA PEL	Exposure Limit (mg/m ³) ACGIH-TLV
Carbon	7440-44-0	3.5 (Carbon Black)	3.5 (Carbon Black)
Copper	7440-50-8*	0.1 (Fume)	0.2 (Fume, as Cu)
Graphite	7782-42-5	2.5 (Respirable Dust)	2 (Respirable Dust)

Occupational Safety and Health Administration 29 CFR 1910.1000 Permissible Exposure Limit (PEL).

American Conference of Governmental Industrial Hygienists (ACGIH)

Threshold Limit Value (TLV[R]).

* A toxic chemical subject to the reporting requirements of Section 313 of the Emergency Planning and community Right-To-Know Act of 1986 (SARA) and 40 CFR Part 372.

SECTION 3: PHYSICAL DATA

Physical State: Solid **Appearance and Odor:** Bare copper coated carbon graphite rods, odorless.

SECTION 4: FIRE AND EXPLOSION HAZARD DATA

Non-Flammable; Welding arc and sparks can ignite combustibles. See Z-49.1 references in Section 6.

SECTION 5: REACTIVITY DATA

Hazardous Decomposition Products

Welding fumes and gases cannot be classified simply. The composition and quantity of both are dependent upon the metal being welded, the process, procedures and electrodes used.

Workers should be aware that the composition and quantity of the fumes and gases to which they may be exposed are influenced by: coatings which may be present on the metal being welded (such as paint, plating or galvanizing), the number of welders in operation and the volume of the work area, the quality and amount of ventilation, the position of the welder's head with respect to the fume plume, as well as the presence of contaminants in the atmosphere (such as chlorinated hydrocarbon vapors from cleaning and degreasing procedure). When the electrode is consumed, the fumes and gas decomposition products generated are different in percent and form from the ingredients listed in Section 2. The composition of these fumes and gases are the concerning matter and not the composition of the electrode itself. Decomposition products include those originating from the volatilization, reaction or oxidation of the ingredients shown in Section 2, plus those from the base metal, coating, and other factors as noted above

Reasonable expected decomposition products from normal use of these products include a complex of the oxides of the materials listed in Section 2, as well as carbon monoxide, carbon dioxide, ozone and nitrogen oxides (refer to "characterization of Arc Welding Fume" available from the American Welding Society).

Gaseous reaction products may include carbon monoxide and carbon dioxide.

Ozone and nitrogen oxides may be formed by the radiation from the arc.

One method of determining the composition and quantity of fumes and gases to which workers are exposed by taking an air sample from inside the welder's helmet while worn or in the worker's breathing zone. See ANSI/AWS F1.1 publication available from the American Welding Society, 550 N.W. LeJeune Road, Miami, FL 33126.

SECTION 6: HEALTH HAZARD DATA

Threshold Limit Value: The ACGIH recommended general limit for Welding Fume NOC-(Not Otherwise Classified) is 5 mg/m³. ACGIH-1985 preface states "The TLC-TWA should be used as guides in the control of health hazards and should not be used as fine lines between safe and dangerous concentrations". See Section 5 for specific fume constituents which may modify this TLV.

Common Entry is by Inhalation or Through the Eyes, Skin Contact and Ingestion.

Effects of Overexposure: Electric arc welding may create one or more of the following health hazards: fume and gases can be dangerous to your health.

Short-term (acute) overexposure to welding fumes may result in discomfort such as metal fume fever, dizziness, nausea or dryness or irritation of nose, throat or eyes. Copper fumes may cause metal fume fever, the symptoms of which are metallic taste, dryness or irritation of the throat, nausea, fever body aches and chills.

Long-term (chronic) overexposure to welding fumes can lead to their accumulation in the lungs, a condition which may be seen as dense areas on chest X-rays. The severity of change is proportional to the length of the exposure. The changes seen are not necessarily associated with symptoms or signs of reduced lung function or disease. In addition, the changes on X-rays maybe caused by non-work factors such as smoking, etc

Exposure limits for the ingredients are listed in Section 2. The 1989 OSHA TWA for welding fume is 5 mg/m³. TLV-TWAs should be used as a guide in the control of health hazards and not as fine lines between safe and excessive concentrations.

Arc Rays can injure eyes and burn skin.

Electric shock can kill.

See Section 7.

Emergency and First Aid Procedures: Call for medical assistance. Use first aid procedures recommended by the American Red Cross. If breathing is difficult give oxygen. IF NOT BREATHING use CPR (Cardiopulmonary Resuscitation).

Carcinogenicity

29 CFR 1910.1200- Hazard Communication Standard lists possible carcinogenic information.

SECTION 7: CONTROL MEASURES AND PRECAUTIONS FOR SAFE HANDLING AND USE

Read and understand the manufacturer's instructions and the precautionary label on the product. See American National Standard Z49.1; Safety in Welding, Cutting published by the American Welding Society, 550 N.W. LeJeune Road, Miami, FL 33126 and OSHA Publication 2206 (29 CFR 1910), U.S. Government Printing Office, Washington D.C. 20402 for more details on the following topics.

Ventilation: Use plenty of ventilation and/or local exhaust at the arc to keep the fumes and gases below the threshold limit value within the worker's breathing zone and the general area. Welders should be advised to keep their head out of the fumes.

Respiratory Protection: Use respirable fume respirator or air supplied respirator when welding in confined space or general work areas when local exhaust or ventilation does not keep exposure below TLV.

Eye Protection: Wear helmet or use face shield with filter lens shade number 12-14 or darker. Shield other workers by providing screens and flash goggles.

Protective Clothing: Wear approved hand, head and body protection which help to prevent injury from radiation, sparks and electrical shock. See ANSI Z49.1. This would include wearing welder's gloves and a protective face shield, and may include arm protectors, apron, hats, shoulder protection as well as dark substantial clothing. Train the welder not to allow electrically live parts to contact skin or wet clothing and gloves. The welder should insulate themselves from the work and ground.

Waste Disposal Method: Discard any product, residue, disposable container or liner in an environmentally acceptable manner approved by Federal, State and Local regulations.

WELDING MATERIAL SALES, Inc. strongly recommends the users of this product study this MSDS, the product label information and become aware of all hazards associated with welding. WELDING MATERIAL SALES, Inc. believes this data to be accurate and to reflect qualified expert opinion regarding current research. However, WELDING MATERIAL SALES, Inc. cannot make any expressed or implied warranty as to this information.